

# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: KEITH MASSIE, Region 10  
Telephone: (757) 889-9436

**RE: FCC NTSC Engineering Database**

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
if Correct

Station Call Sign:	<u>WHR0-TV</u>	<input checked="" type="checkbox"/>
Channel:	<u>15</u>	<input checked="" type="checkbox"/>
Power:	<u>2630</u>	<input checked="" type="checkbox"/>
Antenna Height:	<u>296 M</u>	<input checked="" type="checkbox"/>
RCAMSL:	<u>301 M</u>	<input checked="" type="checkbox"/>
Transmitter Location:		
Latitude:	<u>36.48.32</u>	<input checked="" type="checkbox"/>
Longitude:	<u>76.30.13</u>	<input checked="" type="checkbox"/>
Directional Antenna:	<u>GHT ODD WHR0TV-CP</u>	<input checked="" type="checkbox"/>
Reference Angle:	<u>0.0</u>	<input checked="" type="checkbox"/>

Please provide any necessary corrections in the spaces below:

Station Call Sign: \_\_\_\_\_  
Channel: \_\_\_\_\_  
Power: 2880  
Antenna Height: \_\_\_\_\_  
RCAMSL: \_\_\_\_\_  
Transmitter Location: \_\_\_\_\_  
Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_  
Directional Antenna: HARRIS TWS-30 WAVESTAR  
Reference Angle: \_\_\_\_\_

Station Call Sign: \_\_\_\_\_  
Channel: \_\_\_\_\_  
Power: \_\_\_\_\_  
Antenna Height: \_\_\_\_\_  
RCAMSL: \_\_\_\_\_  
Transmitter Location: \_\_\_\_\_  
Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_  
Directional Antenna: RCA TFU25DAS  
Reference Angle: 285 Degrees True

### FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor Jawil  
FROM: Harold Lawing, Region 10  
Telephone: 518-436-4822  
RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

		Check Here if Correct
Station Call Sign:	<u>WCDC</u>	<input checked="" type="checkbox"/>
Channel:	<u>19</u>	<input checked="" type="checkbox"/>
Power:	<u>263</u>	<input type="checkbox"/>
Antenna Height:	<u>637</u>	<input checked="" type="checkbox"/>
RCAMSL:	<u>1124</u>	<input type="checkbox"/>
Transmitter Location:		
Latitude:	<u>42-38-14</u>	<input checked="" type="checkbox"/>
Longitude:	<u>73-10-07</u>	<input checked="" type="checkbox"/>
Directional Antenna:		<input type="checkbox"/>
Reference Angle:		<input type="checkbox"/>

Please provide any necessary corrections in the spaces below:

Station Call Sign: \_\_\_\_\_  
Channel: \_\_\_\_\_  
Power: 263 KW  
Antenna Height: \_\_\_\_\_  
RCAMSL: 1124 m 3680'  
Transmitter Location: \_\_\_\_\_  
Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_  
Directional Antenna: \_\_\_\_\_  
Reference Angle: \_\_\_\_\_

## FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: FRED BOUDRISAU, Region 10  
 Telephone: 617 787 7063

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

		Check Here if Correct
Station Call Sign:	<u>WBZ-TV</u>	<u>✓</u>
Channel:	<u>4</u>	<u>✓</u>
Power:	<u>60.3 KW</u>	<u>✓</u>
Antenna Height:	<u>354 M</u>	<u>—</u>
RCAMSL:	<u>404 M</u>	<u>—</u>
Transmitter Location:		
Latitude:	<u>42:18:37</u>	<u>✓</u>
Longitude:	<u>71:14:14</u>	<u>✓</u>
Directional Antenna:	<u>NO</u>	<u>✓</u>
Reference Angle:	<u>0</u>	<u>✓</u>

Please provide any necessary corrections in the spaces below:

Station Call Sign:	<u>                    </u>
Channel:	<u>                    </u>
Power:	<u>                    </u>
Antenna Height:	<u>365.5M</u>
RCAMSL:	<u>412. M</u>
Transmitter Location:	
Latitude:	<u>                    </u>
Longitude:	<u>                    </u>
Directional Antenna:	<u>                    </u>
Reference Angle:	<u>                    </u>

## FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWI 202-861-0342

FROM: MARK ARPINO, Region 10  
 Telephone: 508-562-0660

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

		Check Here if Correct
Station Call Sign:	<u>WHSN-TV</u>	<u>✓</u>
Channel:	<u>66</u>	<u>✓</u>
Power:	<u>3630 KW</u>	<u>✓</u>
Antenna Height:	<u>326.0</u>	<u>✓</u>
RCAMSL:	<u>434.0</u>	<u>✓</u>
Transmitter Location:		
Latitude:	<u>42 - 23 - 01</u>	<u>—</u>
Longitude:	<u>71 - 29 - 35</u>	<u>—</u>
Directional Antenna:		<u>—</u>
Reference Angle:		<u>—</u>

Please provide any necessary corrections in the spaces below:

*HART*  
*RADIATION CENTER*

Station Call Sign:	<u>                    </u>
Channel:	<u>                    </u>
Power:	<u>3160 KW</u>
Antenna Height:	<u>                    </u>
RCAMSL:	<u>                    </u>
Transmitter Location:	
Latitude:	<u>42-23-02</u>
Longitude:	<u>71-29-38</u>
Directional Antenna:	<u>                    </u>
Reference Angle:	<u>                    </u>



**VALIDATION OF  
FCC TV ENGINEERING DATA BASE  
(BY REGION)**

**11/20/96**





## FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: KRCB, Region 1  
Telephone: 707-585-8522

**RE: FCC NTSC Engineering Database**

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

**Check Here  
if Correct**

KRCB

22

67.6 KWERP

602.0 HAAT

504

38 20 54

38 20 54

122 34 27

BOG 000830224K1

\_\_\_\_\_

Please provide any necessary corrections in the spaces below:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

100

\_\_\_\_\_

1. *Journal of the American Medical Association*, 1997; 278: 1039-1044.

\_\_\_\_\_

\_\_\_\_\_

CA Region 1

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL  
FROM: STEVE PAIR, Region I  
Telephone: 213) 960-3719  
RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
if Correct

Station Call Sign:	<u>KCAL-TV</u>	_____
Channel:	<u>9</u>	_____
Power:	<u>141 KW-PK ERP</u>	_____
Antenna Height:	<u>6176' AMSL</u>	_____
RCAMSL:	<u>6135'</u>	_____
Transmitter Location:		_____
Latitude:	<u>34° 13' 38" N</u>	_____
Longitude:	<u>118° 04' 00" W</u>	_____
Directional Antenna:	<u>Y</u>	_____
Reference Angle:	<u>225°</u>	_____

Please provide any necessary corrections in the spaces below:

Station Call Sign:	_____
Channel:	_____
Power:	_____
Antenna Height:	_____
RCAMSL:	_____
Transmitter Location:	_____
Latitude:	_____
Longitude:	_____
Directional Antenna:	_____
Reference Angle:	_____

Post-It® Fax Note	7671	Date	10-18	# of pages	1
To	V. TAWIL	From	STEVE PAIR		
Co./Dept.		Co.	KCAL-TV		
Phone #		Phone #	213) 960-37		
Fax #	202) 861-0342	Fax #	213) 464-08		

# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL  
 FROM: KCRA, Region 1  
 Telephone: 916-325-3247  
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
 if Correct

Station Call Sign:	<u>KCRA</u>	<u>    </u>
Channel:	<u>3</u>	<u>    </u>
Power:	<u>100 kw ERP</u>	<u>    </u>
Antenna Height:	<u>2000' MSL</u>	<u>    </u>
RCAMSL:	<u>1950' MSL</u>	<u>    </u>
Transmitter Location:		
Latitude:	<u>38/15/52</u>	<u>    </u>
Longitude:	<u>121/29/22</u>	<u>    </u>
Directional Antenna:	<u>OMNI</u>	<u>    </u>
Reference Angle:	<u>NA</u>	<u>    </u>

Please provide any necessary corrections in the spaces below:

Station Call Sign:	<u>                    </u>
Channel:	<u>                    </u>
Power:	<u>                    </u>
Antenna Height:	<u>                    </u>
RCAMSL:	<u>                    </u>
Transmitter Location:	
Latitude:	<u>                    </u>
Longitude:	<u>                    </u>
Directional Antenna:	<u>                    </u>
Reference Angle:	<u>                    </u>

# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: KQCA, Region 1

Telephone: 916-325-3247

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
if Correct

Station Call Sign:	<u>KQCA</u>	<u>    </u>
Channel:	<u>58</u>	<u>    </u>
Power:	<u>5 MEGAWATT ERP</u>	<u>    </u>
Antenna Height:	<u>1942' MSL</u>	<u>    </u>
RCAMSL:	<u>1842' MSL</u>	<u>    </u>
Transmitter Location:		
Latitude:	<u>38/14/24</u>	<u>    </u>
Longitude:	<u>121/30/03</u>	<u>    </u>
Directional Antenna:	<u>OMNI</u>	<u>    </u>
Reference Angle:	<u>NA</u>	<u>    </u>

Please provide any necessary corrections in the spaces below:

Station Call Sign:	<u>                    </u>	<u>    </u>
Channel:	<u>                    </u>	<u>    </u>
Power:	<u>                    </u>	<u>    </u>
Antenna Height:	<u>                    </u>	<u>    </u>
RCAMSL:	<u>                    </u>	<u>    </u>
Transmitter Location:		
Latitude:	<u>                    </u>	<u>    </u>
Longitude:	<u>                    </u>	<u>    </u>
Directional Antenna:	<u>                    </u>	<u>    </u>
Reference Angle:	<u>                    </u>	<u>    </u>

## FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: MARIWYN LAWRENCE  
 FROM: KCSM, Region 1  
 Telephone: 415 358-6879  
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
if Correct

Station Call Sign:	<u>KCSM</u>	<u>    </u>
Channel:	<u>60</u>	<u>    </u>
Power:	<u>80KW</u>	<u>    </u>
Antenna Height:	<u>70 M</u>	<u>    </u>
RCAMSL:	<u>423 M</u>	<u>    </u>
Transmitter Location:		
Latitude:	<u>37° 41' 07"</u>	<u>    </u>
Longitude:	<u>122° 26' 01"</u>	<u>    </u>
Directional Antenna:	<u>Alan Dick UTA-25 H/V BP</u>	<u>    </u>
Reference Angle:	<u>126° T</u>	<u>    </u>

Please provide any necessary corrections in the spaces below:

Station Call Sign:	<u>                    </u>
Channel:	<u>                    </u>
Power:	<u>                    </u>
Antenna Height:	<u>                    </u>
RCAMSL:	<u>                    </u>
Transmitter Location:	
Latitude:	<u>                    </u>
Longitude:	<u>                    </u>
Directional Antenna:	<u>                    </u>
Reference Angle:	<u>                    </u>

## FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor Tawil

FROM: Massoud Salarvand Region 1  
Telephone: (818) 563-5722

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here  
if Correct

Station Call Sign:	<u>KRCA</u>	X
Channel:	<u>62</u>	X
Power:	<u>3720.0</u>	X
Antenna Height:	<u>723.0</u>	X
RCAMSL:	<u>1684.0</u>	X
Transmitter Location:		
Latitude:	<u>34-11-16</u>	X
Longitude:	<u>117-41-55</u>	X
Directional Antenna:	<u>D1E 0DD911120KE</u>	X
Reference Angle:	<u>0.0</u>	X

Please provide any necessary corrections in the spaces below:

Station Call Sign: \_\_\_\_\_  
Channel: \_\_\_\_\_  
Power: \_\_\_\_\_  
Antenna Height: \_\_\_\_\_  
RCAMSL: \_\_\_\_\_  
Transmitter Location: \_\_\_\_\_  
Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_  
Directional Antenna: \_\_\_\_\_  
Reference Angle: \_\_\_\_\_







# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the information contained in the enclosed FCC NTSC Database is correct for your station:

All the information from station(s) KBSI/WDKA is correct.

(Check one)

       Yes OR X No

Please provide any necessary corrections in the spaces below:

Station Call Sign:	<u>KBSI</u>	<u>WDKA</u>
Channel:	<u>23</u>	<u>49</u>
Power:	<u>      </u>	<u>      </u>
Antenna Height:	<u>540</u>	<u>      </u>
RCAMSL:	<u>694</u>	<u>      </u>

Transmitter Location:

Latitude:         
Longitude:       

Directional Antenna:         
Reference Angle:       

**PLEASE RETURN THIS FORM BY FAX, MAIL, OR RESPOND VIA E-MAIL NO LATER THAN OCTOBER 20, 1996 TO:**

Victor Tawil  
DTV Channel Coordination  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
e-mail: vtawil@delphi.com

AND

Steven A. Smith  
Vice President, Engineering  
Cosmos Broadcasting Corporation  
P.O. Box 19023  
Greenville, SC 29602-9023  
fax: 864-600-4400

TO: Victor Tawil, MSTV

FROM: Don Perez, K\*USA-TV, Region 3  
Telephone: 303-871-1493

RE: FCC NTSC Engineering Database

Check Here  
if Correct

\* Dielectric TW 12A9-R

Station Call Sign:	Same as Above
Channel:	
Power:	
Antenna Height:	
RCAMSL:	
Transmitter Location:	
Latitude:	
Longitude:	
Directional Antenna:	
Reference Angle:	

**FCC NTSC ENGINEERING DATABASE CORRECTION SHEET**

**TO:** Television Station KBIM

**FROM:** Joe Snelson, Region 3, Technical Coordinator  
Telephone: 913-677-7250

**RE:** FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here  
if Correct

State:	NM	<input checked="" type="checkbox"/>
City of License:	ROSWELL	<input checked="" type="checkbox"/>
Station Call Sign:	KBIM	<input checked="" type="checkbox"/>
Channel:	10	<input checked="" type="checkbox"/>
Power:	316 KW	<input checked="" type="checkbox"/>
Antenna Height:	610 mtr.	<input checked="" type="checkbox"/>
RCMSL:	1893 mtr.	<input checked="" type="checkbox"/>
Transmitter Location:		
Latitude:	33 03 20	<input checked="" type="checkbox"/>
Longitude:	103 49 12	<input checked="" type="checkbox"/>
Directional Antenna:	No	<input checked="" type="checkbox"/>
Reference Angle:		<input checked="" type="checkbox"/>

Please provide any necessary corrections in the spaces below:

State:	
City of License:	
Station Call Sign:	
Channel:	
Power:	
Antenna Height:	
RCMSL:	
Transmitter Location:	
Latitude:	
Longitude:	
Directional Antenna:	
Reference Angle:	

**PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:**

Victor Tawil  
DTV Channel Coordinator  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
email: vtawil@delphi.com

**Victor Tawil**  
**DTV Channel Coordinator**  
**MSTV**  
**Suite 310**  
**1776 Massachusetts Avenue, N.W.**  
**Washington, D.C. 20036**  
**fax: 202-861-0342**  
**email: vtawil@delphi.com**

**FCC NTSC ENGINEERING DATABASE CORRECTION SHEET**

**TO:** Television Station KZIA

**FROM:** Joe Snelson, Region 3, Technical Coordinator  
Telephone: 913-677-7250

**RE:** FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here  
if Correct

State:	NM	<input checked="" type="checkbox"/>
City of License:	LAS CRUCES	<input checked="" type="checkbox"/>
Station Call Sign:	KZIA	<input checked="" type="checkbox"/>
Channel:	48	<input checked="" type="checkbox"/>
Power:	5000 KW	<input checked="" type="checkbox"/>
Antenna Height:	134 mtr.	<input checked="" type="checkbox"/>
RCMSL:	1399 mtr.	<input checked="" type="checkbox"/>
Transmitter Location:		
Latitude:	32 02 30	<input checked="" type="checkbox"/>
Longitude:	106 27 41	<input checked="" type="checkbox"/>
Directional Antenna:	Yes	<input checked="" type="checkbox"/>
Reference Angle:		<input checked="" type="checkbox"/>

Please provide any necessary corrections in the spaces below:

State:	_____
City of License:	_____
Station Call Sign:	_____
Channel:	_____
Power:	_____
Antenna Height:	_____
RCMSL:	_____
Transmitter Location:	_____
Latitude:	_____
Longitude:	_____
Directional Antenna:	_____
Reference Angle:	_____

**PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:**

Victor Tawil  
DTV Channel Coordinator  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
email: vtawil@delphi.com

# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Television Station KASY

FROM: Joe Snelson, Region 3, Technical Coordinator  
Telephone: 913-677-7250

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here  
if Correct

State:	NM	<input checked="" type="checkbox"/>
City of License:	ALBUQUERQUE	<input checked="" type="checkbox"/>
Station Call Sign:	KASYTV	<input checked="" type="checkbox"/>
Channel:	50	<input checked="" type="checkbox"/>
Power:	1410 KW	<input checked="" type="checkbox"/>
Antenna Height:	1276 mtr.	<input checked="" type="checkbox"/>
RCMSL:	3289 mtr.	<input checked="" type="checkbox"/>
Transmitter Location:		
Latitude:	35 12 40	<input checked="" type="checkbox"/>
Longitude:	106 26 57	<input checked="" type="checkbox"/>
Directional Antenna:	No	<input checked="" type="checkbox"/>
Reference Angle:		<input checked="" type="checkbox"/>

Please provide any necessary corrections in the spaces below:

State:	_____
City of License:	_____
Station Call Sign:	_____
Channel:	_____
Power:	_____
Antenna Height:	_____
RCMSL:	_____
Transmitter Location:	_____
Latitude:	_____
Longitude:	_____
Directional Antenna:	_____
Reference Angle:	_____

PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:

Victor Tawil  
DTV Channel Coordinator  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
email: vtawil@delphi.com

Victor Tawil  
DTV Channel Coordinator  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
email: vtawil@delphi.com

# FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Television Station KZIA

FROM: Joe Snelson, Region 3, Technical Coordinator  
Telephone: 913-677-7250

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

		Check Here if Correct
State:	NM	<input checked="" type="checkbox"/>
City of License:	LAS CRUCES	<input checked="" type="checkbox"/>
Station Call Sign:	KZIA	<input checked="" type="checkbox"/>
Channel:	48	<input checked="" type="checkbox"/>
Power:	5000 KW	<input checked="" type="checkbox"/>
Antenna Height:	134 mtr.	<input checked="" type="checkbox"/>
RCAMSL:	1399 mtr.	<input checked="" type="checkbox"/>
Transmitter Location:		
Latitude:	32 02 30	<input checked="" type="checkbox"/>
Longitude:	106 27 41	<input checked="" type="checkbox"/>
Directional Antenna:	Yes	<input checked="" type="checkbox"/>
Reference Angle:		

Please provide any necessary corrections in the spaces below:

State:	_____
City of License:	_____
Station Call Sign:	_____
Channel:	_____
Power:	_____
Antenna Height:	_____
RCAMSL:	_____
Transmitter Location:	_____
Latitude:	_____
Longitude:	_____
Directional Antenna:	_____
Reference Angle:	_____

PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:

Victor Tawil  
DTV Channel Coordinator  
MSTV  
Suite 310  
1776 Massachusetts Avenue, N.W.  
Washington, D.C. 20036  
fax: 202-861-0342  
email: vtawil@delphi.com

Post-It Fax Note	7671	Date 10-24-96	Page 1
	To Ray DePa From Joe Snelson Ca		



